

Superfund Site Strategy Recommendation

Region 6 *h*

Site Name: Exxon Co-USA Refinery Site Number: TXD000782698

Alias Site Name(s): _____

Address: Decker Dr. near Intersection w/ Hwy 201

City/County or Parish/State/Zip: Baytown TX (Harris County) 77520

Recommendation:

☐ 1. No further action needed; no hazardous waste problem.

☐ 2. No further remedial action planned under Superfund; site would not score high enough using the Hazard Ranking System to be considered for the National Priorities List.

☒ 3. No further remedial action planned Under Superfund; action may be appropriate under other authority: RCRA ☒ NPDES _____ SPCC _____
404 _____ TSCA _____ UIC _____ SMCRA _____ State _____
Other _____

☐ 4. Further pre-remedial investigative action needed under Superfund:

PA _____
SSI _____ Priority: High _____ Medium _____
LSI _____
Other _____
To be performed by _____

Discussion:

See Attachment

SUPERFUND FILE

JAN 04 1993

REORGANIZED

Exxon - Baytown

TXD000782698

Copies to (please list): 604-140

Recommended By: David Thompson (64-ES) Date: 9/2/88

Approved By: Lesley R. Hatcher Date: 9-7-88

Exxon Co. USA-Baytown Refinery (TXD000762698)
02/02/88

Recommendation: No further remedial action planned under
Superfund; action may be more appropriate under other RCRA

Discussion:

The Exxon Co. USA - Baytown Refinery is a refinery which has been active since 1919. The refinery transforms crude oil and other raw materials into refined hydrocarbon products. This site was identified through a CERCLA notifier; but the facility is classified as a TSD (treatment, storage, disposal) facility under the RCRA regulations. In addition, a RFA (RCRA facility assessment) report conducted for this facility recommended a RFI (RCRA facility investigation). Since this facility is being regulated by RCRA and is also being evaluated for possible corrective action, there is no need for any further investigation by Superfund.

D.G.
9/2/88.